



GARONY - FRANCE TEAM BASE CAMP



PITCH & FACILITY CONDITION REPORTS

JULY 2021

An inspection was carried out by ProPitch to review the condition of the pitch at the Gardony Team Base Camp ahead of the arrival of the France National Team for UEFA Euro 2020.

The pitch was found to be in poor repair as a result of a lack of / substandard irrigation system, high temperatures and high winds. This resulted in extremely dry, compacted and hydrophobic soil conditions giving rise to highly drought stressed turf and, in certain areas, an almost complete loss of grass cover.

The pitch was deemed unfit for purpose at the time of inspection. ProPitch detailed an intensive remedial programme to bring the pitch up the required standard.




SEVERE HEAT AND DROUGHT STRESS



IRRIGATION PRESSURE



RECOMMENDED EQUIPMENT



EXPOSED SOCKETS

Emergency Assessments

International Support

Improvement Plans

Player Safety Inspections